

Spring Course Schedule			
MARCH	APRIL	MAY	JUNE
<p>FEB 27 - MAR 11 LOCATION: <u>DRYDEN</u> DEADLINE: FEB 10 GED EXAMS: MAR 10, 11 GED</p>	<p>APR 4, 5, 6 LOCATION: <u>DRYDEN</u> DEADLINE: MAR 31 Practices and Procedures for WD (0.7 CEU) Pumping Stations and Hydraulics (0.6 CEU) Tapping of Water Mains (0.6 CEU)</p>	<p>MAY 9, 10, 11 LOCATION: <u>DRYDEN</u> DEADLINE: MAY 5 Trenching and Excavation Safety (0.7 CEU) Piping and Water Main Installation (0.7 CEU) Controlling Corrosion (0.7 CEU)</p>	<p>JUN 6, 7 LOCATION: <u>DRYDEN</u> DEADLINE: JUN 2 Backflow Prevention and Cross Connection Control (1.4 CEUs)</p>
<p>MAR 14, 15, 16 LOCATION: <u>DRYDEN</u> DEADLINE: MAR 10 Water Sources and Characteristics (0.5 CEU) Intro to SWP (0.4 CEU) Jar Testing (0.7 CEU) Processes for WT (0.7 CEU)</p>	<p>APR 11, 12, 13 LOCATION: <u>NIPIGON</u> DEADLINE: APR 7 Practices and Procedures for WD (0.7 CEU) Pumping Stations and Hydraulics (0.6 CEU) Tapping of Water Mains (0.6 CEU)</p>		<p>JUN 13, 14 LOCATION: <u>DRYDEN</u> DEADLINE: JUN 9 Backflow Prevention and Cross Connection Control (1.4 CEUs)</p>
<p>MAR 20-24 LOCATION: <u>DRYDEN</u> DEADLINE: FEB 24 OWWCO EXAM: MAR 24 OIT - WT/WD I-II-III (2.6 CEUs)</p>	<p>APR 24-28 LOCATION: <u>DRYDEN</u> DEADLINE: MAR 28 OWWCO EXAM: APR 28 OIT - WT/WD I-II-III (2.6 CEUs)</p>	<p>MAY 15-19 LOCATION: <u>DRYDEN</u> DEADLINE: APR 19 OWWCO EXAM: MAY 19 OIT - WT/WD I-II-III (2.6 CEUs)</p>	<p>JUN 19-23 LOCATION: <u>DRYDEN</u> DEADLINE: MAY 23 OWWCO EXAM: JUN 24 OIT - WT/WD I-II-III (2.6 CEUs)</p>
<p>MAR 28, 29, 30 LOCATION: <u>NIPIGON</u> DEADLINE: MAR 24 Water Sources and Characteristics (0.5 CEU) Intro to SWP (0.4 CEU) Jar Testing (0.7 CEU) Processes for WT (0.7 CEU)</p>		<p>MAY 23, 24, 25 LOCATION: <u>NIPIGON</u> DEADLINE: MAY 19 Trenching and Excavation Safety (0.7 CEU) Piping and Water Main Installation (0.7 CEU) Controlling Corrosion (0.7 CEU)</p>	